

Work Order ID 74084

Wednesday, September 21, 2011 10:50:18 A



Page 1

Item ID: D412-702-311

Accept



Setup Start



Revision ID:

Stop



Item Name: Harness Assembly

Start Date: 9/22/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 10/6/2011 Req'd Qty: 1.00



Customer:

Reference:

Run Start



Approvals: Process Plan: MF Date: 11-09-21 Tooling: _____ Date: _____

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
DSI 9511	A

100 0.00



Small Fab

Memo

0.00

Small Fab

Assemble as per dwg ICA D412-702 p.49

EP 11/09/21 ①

110 QC5- Inspect part completeness to step on W/O 0.00



QC

Memo

0.00

Quality Control

8 ul 9/21

XL

120 0.00



Packaging

Memo

0.00

Packaging

Identify with P/N & CHG# and pack for shipping as per PPP D412-702-311

CHG001

Location: 262

PPP Rev: _____

11/9/21 8

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 74084

Page 2

Wednesday, September 21, 2011 10:50:18 A

Item ID: D412-702-311

Accept



Setup Start



Revision ID:

Stop



Item Name: Harness Assembly

Start Date: 9/22/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 10/6/2011 Req'd Qty: 1.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

130

QC21- Final Inspection - Work Order Release

0.00




QC

Memo

0.00

Quality Control

11/9/22 
MF
11-09-22

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Wednesday, September 21, 2011 10:50:16 AM

Page 1

[illegible]

Required Date: 10/6/2011

Required Qty: 1.00

Comments: IPP Rev:A new issue DD 10.04.30 verified:EC

[illegible]

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Wednesday, September 21, 2011 10:50:16 AM

Page 2

Work Order ID: 74084



Parent Item: D412-702-311



Parent Item Name: Harness Assembly

Start Date: 9/22/2011

Required Date: 10/6/2011

Start Qty: 1.00

Required Qty: 1.00

MS21042L3

Purchased

No

100

Each

2,592.000

4

4



Nut

JS 11/09/21

Location

Loc Qty

Loc Code

ST300

2592

117441

24

117601

363

117885

205

118451

1000

118927

1000

4


W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____


Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



**DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-117A AND
D412-702-101B/-103B/-105B/-107B/-109B/-115B/-117B OR -301/-303/-305/-
307/-309/-315/-317 HARNESS ASSEMBLIES**



DETAIL 'L' D412-702-111A/-111B/-113A/-113B OR -311/-313/-321/-323 HARNESS ASSEMBLIES

• COPYRIGHT © 2004 BY DART AEROSPACE LTD. •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR
COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

25-00-00

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries